924575

FINAL REPORT FOR REMEDIATION OF LOCATIONS IN GRANITE CITY, MADISON, AND VENICE, ILLINOIS ASSOCIATED WITH NL INDUSTRIES/TARACORP SUPERFUND SITE

PRE-PLACED CONTRACT NO.

DACA45-96-D-0014

DELIVERY ORDER NO. 0005

Submitted by:

OHM Remediation Services Corp. *Midwest Region*

Prepared by:

Tom Warren Project Manager

October 16, 1998 Project 19531

This information is the exclusive property of the party to whom it is addressed. OHM Remediation Services Corp. assumes no responsibility or liability for the reliance hereon or use hereof by anyone other than the party to whom it is addressed. ©1998 OHM Remediation Services Corp.

260893

TABLE OF CONTENTS

- 1.0 INTRODUCTION
 - 1.1 SITE HISTORY
 - 1.2 DOCUMENT ORGANIZATION
- 2.0 SCOPE OF WORK
 - 2.1 PREPARATION OF SITE-SPECIFIC PLANS
 - 2.2 SITE ADMINISTRATION/LOGISTICAL SUPPORT
 - 2.3 MOBILIZATION/DEMOBILIZATION
 - 2.4 SITE PREPARATION AND TEARDOWN
 - 2.5 OPERATIONAL SCOPE OF WORK PERFORMED
 - 2.6 SAMPLING AND ANALYSIS
 - 2.7 TRANSPORTATION AND DISPOSAL
- 3.0 TECHNICAL APPROACH
 - 3.1 PRE-CONSTRUCTION ACTIVITIES
 - 3.2 SAMPLING AND ANALYSIS
 - 3.3 CHEMICAL DATA ACQUISITION PLAN AMENDMENTS/ADJUSTMENTS
 - 3.4 TRANSPORTATION AND DISPOSAL
- 4.0 HEALTH AND SAFETY SUMMARY
 - 4.1 PROJECT SUMMARY AND CONCLUSIONS
 - 4.2 SITE SAFETY AND HEALTH PLAN EVALUATION
 - 4.3 SITE SAFETY
 - 4.4 EXPOSURE MONITORING
- 5.0 QUANTITY SUMMARY TABLE
- 6.0 VERIFICATION ANALYTICAL SUMMARY TABLE
 - 6.1 STACK EMISSION SITES
- 7.0 PHOTO REPRESENTATION

APPENDIX A - FLOW CHARTS
APPENDIX B - REMEDIAL LOCATION WORK DESCRIPTIONS
APPENDIX C - EASEMENT INFORMATION

1.0 INTRODUCTION

The United States Army Corps of Engineers (USACE) tasked OHM Remediation Services Corp. (OHM), a wholly owned subsidiary of OHM Corporation, under the Pre-Placed Contract No. DACA45-96-D-0014, Delivery Order (DO) No. 005, to perform remediation of Stack Emission sites at various locations associated with the NL Industries/Taracorp Superfund Site (NL Site) in Granite City, Madison, and Venice, Illinois.

1.1 SITE HISTORY

The NL Site includes the NL Industries/Taracorp Plant, a former secondary lead smelting operation located at 16th and Cleveland Boulevard in Granite City, Illinois. Prior to 1903, the plant included various smelting related equipment and processes. From 1903 to 1983, secondary lead smelting occurred on site. These activities were discontinued during 1983 and the equipment was dismantled.

In July 1981, St. Louis Lead Recyclers, Inc. (SLLR) began using equipment on adjacent property owned by Trust 454 to separate components of the Taracorp waste pile. The objective was to recycle lead bearing materials to the furnaces at Taracorp and send hard rubber off site for recycling. SLLR continued operations until March 1983 when it shut down its equipment. Residuals from the operation remain on Trust 454 property as does some equipment.

A State Implementation Plan for Granite City, Illinois was published in September 1983 by the Illinois Environmental Protection Agency (IEPA). The IEPA's report indicated the lead non-attainment problem for air emissions in Granite City, Illinois, were in large part due to emissions associated with the operation of the secondary lead smelter operation by Taracorp and lead reclamation activities conducted by SLLR. The IEPA procured Administrative Orders by Consent with Taracorp, SLLR, Stackorp, Inc., Tri-City Truck Plaza, Inc., and Trust 454 during March 1984. The orders required the implementation of remedial activities relative to air quality.

NL Industries, as former owner of the location, voluntarily entered into an Agreement and Administrative Order by Consent with United States Environmental Protection Agency (USEPA) and IEPA in May 1985 to implement a Remedial Investigation/Feasibility Study (RI/FS) for the location and other potentially affected areas. Taracorp was not a party to the agreement due to the fact it filed for bankruptcy. The USEPA determined the location was a Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) facility and it was placed on the National Priorities List on June 19, 1986.

1.2 DOCUMENT ORGANIZATION

This final project report is intended to provide a detailed description of the tasks involved in performing the work. Section 2.0 describes the scope of work involved in the preparation of the site-specific plans, performance of site administration/logistical support, mobilization/demobilization, site preparation/teardown, and the operational/technical scope of work performed. Section 2.0 also compares the actual scope of work performed with the planned scope of work in general terms. Section 3.0 describes the technical approaches implemented to accomplish the operational and technical tasks of the project including

sampling, analysis, waste transportation, and waste disposal. Section 4.0 describes the Health and Safety approaches implemented to accomplish the operational tasks of the project. Section 5.0 and 6.0 contain the quantity summary tables and verification analytical summary tables respectively. Appendix A depicts the Flow Charts showing work performance. Appendix B provides detailed descriptions of the work performed at each remedial location, as well as, tables and maps detailing the sampling and analysis. Appendix C contains the detailed descriptions of work performed on the easements for this project.

2.0 SCOPE OF WORK

The scope of work for this project was delineated by the documents USACE supplied to OHM entitled: Scope of Work for Contract DACA45-95-R-0015, Stack Emissions (Lead) Removal, Madison, Illinois.

The scope of work generally encompassed the following tasks:

- Preparation of site-specific plans
- Site administration and logistical support
- Mobilization and demobilization
- Site preparation and teardown
- Excavation, Backfill, and Compacting
- Turf
- Operational scope of work
- Waste transportation and disposal

2.1 PREPARATION OF SITE-SPECIFIC PLANS

OHM revised the site-specific project work plan (WP) from DO 17 to serve as a guideline describing how the work was to be performed in order to meet the requirements specified by USACE. The WP also included the chemical data acquisition plan (CDAP) and the location-specific health-and-safety plan (LSSHP).

Variances to the WP occurred during the project but were conducted only under authorization/direction of the USACE on-site representative(s). His/her purpose was to allow the project to function more efficiently while still remaining within all regulatory requirements. These variances are referenced and described in the relevant sections of this report.

The CDAP was prepared as a guideline to describe how, where, and how many samples would be collected. The laboratory analysis methods to be used, per the requirement of USACE's revised scope of services, were also outlined in the CDAP. In response to existing field conditions, this CDAP was amended to add the quality assurance project plan (QAPP) during the actual performance of work (see Section 2.6 for these amendments).

The LSSHP was prepared as a guideline describing the health and safety procedures which would be followed during the performance of the project. LSSHP addressed physical, chemical, and environmental hazards unique to this project site. This LSSHP was amended prior to the project to allow remedial work to

be performed by personnel wearing modified USEPA Level D personal protective equipment (PPE). The results of air monitoring indicated personnel could safely perform work at the remedial locations wearing poly tyvek suits, booties, gloves, hard hats, and safety glasses without respirators. Details pertaining to health and safety issues are discussed in Section 4.0, Health and Safety Summary.

2.2 SITE ADMINISTRATIONAL/LOGISTICAL SUPPORT

The project site administration was centrally located at # 10 Farrish in Madison, Illinois. Site administrative activities performed from this location included:

- Site Supervisor
- Cost tracking/reporting
- · Health and Safety administration
- Waste tracking/documentation
- Field sampling/analytical support
- Field purchasing/subcontract management
- Logistical support

Prior to the physical work, logistical preparation activities were performed, including the following activities:

- Conduct a pre-construction meeting
- Verifying waste hauling licenses
- · Meeting with property owners
- Locating utilities at necessary sites
- Establishing transportation routes
- Coordinating with local agencies and hospital

2.3 MOBILIZATION/DEMOBILIZATION

OHM performed mobilization of personnel and equipment primarily from its facility in O'Fallon, Missouri. A large percentage of the heavy equipment utilized on this project came from local vendors acting as subcontractors.

2.3.1 Subcontractors

Subcontractor activities were managed by the OHM project manager and site supervisor, and by USACE when necessary. Subcontractors were responsible for transportation, disposal, backfill material, sod and on-site equipment.

2.3.2 Permits

All necessary permits and licenses were secured before site mobilization. The transporter companies and disposal facilities were USEPA-licensed. Prior to mobilization, all on-site employees completed

Occupational Safety and Health Administration (OSHA) 40-hour hazardous material training.

2.4 MOBILIZATION/DEMOBILIZATION

Sites were set up and/or torn down at each remedial lot.

2.4.1 Command Center

The command center served as the central location from which all personnel were dispatched to their respective work locations each day or as needed. The command center was located inside of a secured building and was equipped with computers, copiers, facsimile machine, telephones, and base radio. The rear of the building also served as a storage area for OHM's equipment, tools, and materials.

2.4.2 Remedial Locations

Site preparation was performed at each of the remedial locations. OHM set up decontamination points for personnel and equipment and exclusion zones were established prior to excavation. These exclusion zones were identified with orange snow fencing and yellow caution tape across existing fencing. They remained in place until backfill had been completed to a sufficient depth.

Excavation equipment used on the site was decontaminated prior to demobilization or backfill. Gross contamination was scraped from the machines before they were washed. As a dust control measure, the decontamination rinse water was collected and applied to the last load of contaminated soil.

2.5 OPERATIONAL SCOPE OF WORK PERFORMED

The excavation activities involved the removal of contaminated soils from the remedial sites. Restoration involved backfilling, seeding, and sodding of the sites after completing the remedial activities. The scope of work for this portion of the project is illustrated in Figure 2.1.1 The operations Flow Chart is depicted in Appendix A-1.

OHM's schedule for excavation was developed to facilitate logistical management and limit the time required to transport equipment and crews from location to location. During excavation activities, engineering controls and security measures, such as surrounding the exclusion zones with fluorescent orange polyvinyl chloride (PVC) barrier fencing, were employed to prevent cross contamination and unauthorized entry into exclusion zones.

Each of the stack emission sites had unique characteristics, which mandated particular methodologies of remediation.

2.5.1 Pre-construction Activities

Pre-construction activities for this portion of the project included the following items:

- Conducting a pre-construction meeting with USACE
- Issuing subcontracts
- Communication with Julie Corporation (the utilities' identification organization in Illinois) to locate potential underground utilities at the site
- Obtaining permits
- Obtaining soil samples for waste characterization
- Videotaping residential properties for restoration purposes

2.5.2 Construction Activities-Lots

The excavation techniques employed at each location varied according to location accessibility, depth, and extent of material. Minimization of disturbances to adjoining properties/areas was also a key consideration in performing each excavation. OHM used Bobcat mini-excavators, TL26, Takeuchi, TCM806 along with Kubota Tractors and manual removal methods.

Dust control was a major consideration. A storage system with pump and hose were available at all times to prevent fugitive emissions. Water trucks were also utilized to provide additional dust control and to transport water to sites for decontamination.

Most of the residential yards needed to have sod removed at varying depths of soil. Wastes were excavated using a track excavator, Takeuchi, and/or a Bobcat. At some locations, hand digging was necessary. Special soil was loaded into licensed waste hauler trucks for transportation to the disposal facility.

Most of the driveways contained aggregate soil mixtures. Most locations were accessible but required smaller equipment and hand digging. Non-hazardous waste (special waste) was classified analytically. The special waste was loaded into licensed haul trucks and sent to the disposal site.

2.5.4 Restoration

After excavation to predetermine depth had been achieved, OHM restored the location to preremedial conditions. Excavation areas were backfilled with clean soil and restoration was completed as required by the specifications. Sodding, seeding, and revegetation were performed when necessary.

2.5.5 Waste Removal

Wastes removed from the sites were transported to one of two locations. Milam RDF/Chain of Rocks. Figure A-2 in Appendix A shows the flow chart for T&D.

2.6 SAMPLING AND ANALYSIS

The following paragraphs detail the sampling and analysis tasks, as well as CDAP amendments/adjustments

2.6.1 Sampling and Analysis Tasks

The sampling and analysis tasks for this project involved the following items:

- Street Sweeping
- Pre-characterization sampling and analysis of sites included as delineated by USACE
- Pre-characterization sampling and analysis of additional sites
- Resample (stack emission) as directed by USACE
- Backfill sampling

Street Sampling

OHM collected random grab samples from streets, as directed by USACE, for the purpose of determining the lead content of the street.

As per the scope of services issued to OHM by USACE, material at the residential sites exhibiting concentrations of total lead greater than 500 mg/kg were to be removed and disposed.

Samples were collected from one point in the front yard and one point in the back yard. Both samples collected were at least 10 feet from any structures if possible

Site Pre-Characterization Sampling and Analysis

As the project progressed, the need to establish the level of effort anticipated for each upcoming site became much more apparent. The need to pre-characterize each of the remedial locations to establish reasonable estimates of non-hazardous waste requiring removal was made evident via an amendment to the CDAP. The site pre-characterization sampling and analysis efforts were applied to non-hazardous (stack emission) sites. The primary purpose of these efforts was to confirm or refute the potential contamination at each remedial location and to obtain an indication of the extent of contamination at sites with lead concentrations greater than 500 mg/kg. The most efficient and productive approaches to the pre-characterization sampling and analysis, which include the steps described in the following paragraphs, were ultimately developed for the residential lots.

Pre-characterization sampling and analysis at the residential lots included the establishment of two sample locations at each site. The two sample points were positioned at the center of the front and back yard of each location. One sample was then collected at the following depths from each sample location: 0 to 3 inches, 3 to 6 inches, and 6 to 12 inches.

The laboratory analysis of the samples followed the logic as below. The two samples representing the top 3-inch layer of each of the locations were analyzed for total lead and toxicity characteristic leaching

procedure (TCLP) lead. The second and third set (representing 3 to 6 and 6 to 12 inch depths) were analyzed for total lead only.

This is depicted in Figure A-3 in Appendix A.

Pre-characterization of Additional Sites

Under authorization of USACE, OHM performed the pre-characterization sampling of additional sites over and above the original scope of services. The objective of this was to determine the potential presence of lead contamination with anticipation for the planning of remediation at these same sites. The technical approach for this task involved the same approaches as mentioned in the preceding paragraphs concerning pre-characterization.

2.6.2 CDAP Amendment/Adjustments

Development of the Sampling for Backfill Material

An amendment for the sampling and analysis of backfill was designed to show that incoming backfill material was clean to USEPA standards. This was done as a composite sample on every 1000 cubic yards of backfill and run for the following analysis:

- TCLP for Cd, Cr, Pb
- PAH-IEPA Levels
- Pesticides/PCB's
- TPH
- GRO
- DRO
- Total VOC's

2.7 TRANSPORTATION AND DISPOSAL

The transportation and disposal (T&D) of waste from the sites included the shipment of non-hazardous waste shipped to the Chain of Rocks facility/Milam facility. The special waste was transported by Garcia Trucking. The transportation of the waste was performed with tandem dump trucks.

2.7.1 Transportation of Waste

Each site was identified by an address which was written on the manifest. The site was then assigned a 5-digit manifest document number at the time of shipment. This system ensured the trucks origin was documented.

The State of Illinois requires each special waste shipment be on an all Illinois manifest. This allowed each shipment of special waste to also be cross-referenced with the preprinted Illinois manifest document.

2.7.2 Disposal of Wastes

This project involved the removal and disposal of special non-hazardous industrial waste (non-hazardous waste) which was primarily removed from residential locations. The objective of the non-hazardous waste excavation efforts was to remove all material exhibiting concentration of total lead above 500 mg/kg, but less than 5 mg/l, when analyzed by TCLP.

Disposal characterization of waste was determined by analyzing composite samples, as directed in Section 2.6. Pre-characterization analysis was done at each site to verify depth of lead contamination. The characterization of certain waste as non-hazardous was confirmed at each site with the performance of TCLP lead analysis of composite samples.

The disposal facility subcontracted to provide non-hazardous waste disposal was the Chain of Rocks facility/Milam. OHM obtained the approved waste profile by providing analytical that was previously performed under the Rapid Response Contract.

3.0 TECHNICAL APPROACH

The stated objective of this project was to excavate and dispose of lead contaminated soil in yards of residential communities as per the Record of Decision between the USEPA, IEPA, and the potentially responsible parties (PRPs) for the Superfund site.

This section describes the general approach implemented to complete the work in the residential lots. The methods implemented to perform the work on this project fall into one category:

Residential lots (Non-Hazardous)

The operational effort extended was supported by the technical information that was gained through implementation of the following:

- CDAP amendment/adjustment
- Transportation and disposal, Appendix A-2

3.1 PRE-CONSTRUCTION ACTIVITIES

The pre-construction activities performed during this project were predominantly associated with obtaining disposal permits; obtaining transportation permits; preparing and delivering notifications of work to the public; attending public meetings; and identifying utilities at each remedial location. Many of these pre-construction activities were performed on an on-going basis as the project proceeded from one remedial location to the next.

The permits for the disposal of non-hazardous waste were obtained prior to shipment of the waste.

Before work progressed from one remedial location to the next, the identification of utilities was coordinated from the command center by OHM's safety supervisor. The identification of the utilities was coordinated with Julie Corporation. OHM's safety supervisor would telephone Julie Corporation and notify the organization of OHM's intention to perform work at a given site. Julie Corporation would then issue a "dig number" to OHM and notify all utility companies listed to provide service for the area of concern. Typically, the utility companies would mark the utilities on the site within 48 hours of OHM's initial contact with Julie Corporation.

OHM's subcontractors who performed the transportation of waste and equipment at and through the cities of Madison, Venice, and Granite City, Illinois City obtained required transportation permits

3.2 SAMPLING AND ANALYSIS

The sampling and analysis tasks involved the following items:

- Laboratory confirmation sampling and analysis
- Pre-characterization sampling and analysis
- Backfill sampling

As per the direction of USACE, material at the residential sites exhibiting concentrations of total lead greater that 500 mg/kg were removed and disposed.

3.2.1 Pre-Characterization Sampling and Analysis

As the project progressed, the need to establish the level of effort anticipated for each upcoming site became much more apparent. The need to pre-characterize each of the remedial locations for establishing reasonable estimates of non-hazardous waste requiring removal was made evident through incorporation into the CDAP. The site pre-characterization sampling and analysis efforts were applied to non-hazardous (stack emission) sites. The primary purpose of the pre-characterization sampling was to confirm présence of non-hazardous waste meeting the action level. The most effective and productive approaches to the pre-characterization sampling and analysis were ultimately developed for the residential lots.

3.2.2 Technical Approach to Stack Emission Lots

The technical approach to the stack emission lots differed from the residential battery casing cleanups in the respect no confirmation sampling was necessary. The reason for this was due to previous sampling results yielding a pre-determined depth per USEPA. Consequently, yards were excavated to this pre-determined depth. In addition, all waste was shipped out as special-direct to a landfill.

3.3 CHEMICAL DATA ACQUISITION PLAN AMENDMENTS/ADJUSTMENTS

3.3.1 Development of the Sampling for Backfill Material

An amendment for the sampling and analysis of backfill material was designed to show that incoming backfill material was clean to USEPA standards. This was done as composite samples on every 1000 cubic feet of backfill and run for the following analysis:

- TCLP for Cd, Cr, Pb
- PAH-IEPA Levels
- Pesticides/PCB's
- TPH
- GRO
- DRO
- Total VOC's

3.4 TRANSPORTATION AND DISPOSAL

The T & D of waste removed from the sites included the shipment of non-hazardous waste by Garcia Trucking to Chain of Rocks Landfill/ Milam in Granite City, IL.

3.3.1 Transportation of Waste

Each site was identified by an address, which was written on the manifest. The site was then assigned a 5-digit manifest document number at the time of shipment. This system ensured the trucks origins were documented.

3.3.2 Disposal of Wastes

Disposal characterization of the waste was determined by analyzing composite samples, as described in Section 2.6. Verification of waste characterization was performed at each site through pre-characterization efforts. The characterization of certain waste as non-hazardous was confirmed at each site with the performance of total lead and TCLP lead analysis of composite samples.

The disposal facility subcontracted to provide non-hazardous waste disposal was Chain of Rocks/Milam in Granite City, IL. OHM obtained the approved waste profile by providing analytical that was previously done under Rapid Response Contract.

4.0 HEALTH AND SAFETY SUMMARY

4.1 PROJECT SUMMARY AND CONCLUSIONS

4.1.1 Summary

The following summarizes the health and safety aspects of this project:

- Task-specific hazard evaluations were performed each day at each work site prior to the start of work
- Air monitoring data was used during this project to verify appropriate personal protection was being used for site conditions. Personnel medical monitoring was performed prior to and at the end of the project to determine lead levels in the blood.
- Perimeter samples indicated total lead concentration below the action limit established in the LSSHP. Although results obtained are "after the fact," no personnel or citizens were at risk to exposure at any time.
- Personnel air sampling data indicated no detectable reading for total lead. There were no recorded cases of personnel overexposure to ambient lead levels.

4.1.2 Conclusions

Following completion of the project, the OHM Health and Safety Department made the following conclusions:

- The LSSHP was effectively implemented to address the health and safety hazards associated with each phase of site operations and to meet the requirements set forth in 29 CFR 1910.120.
- The existing LSSHP is appropriate for future phases of work at this site involving the same work activities.
- Future work should be performed in Level D PPE with appropriate air monitoring to verify the selection of PPE. An action level of 30mg/m3 should be used to warrant controls. Once monitoring shows consistent reading below the action level, the amount and frequency of air monitoring may be appropriately limited/reduced.
- Special attention should be paid to prevent any recordable accidents and near misses during the course of future work. Routine tasks should be reviewed and evaluated for potential hazards.

4.2 SITE SAFETY AND HEALTH PLAN EVALUATION

A LSSHP was issued before the start of this project to address the health and safety hazards

associated with each phase of site operations. The plan met the requirements of 29 CFR 1910.120. The phases of work addressed in the LSSHP include the following:

- Mobilization
- Installation of perimeter fence
- Soil sampling
- Excavation of contaminated soil
- Load-out of contaminated soil
- Backfill of excavation
- Restoration of disturbed areas
- Decontamination and demobilization

4.2.1 Provisions

Once on site, waste materials were designated to be directly loaded into dump trucks.

Provisions were made to address heavy equipment, excavation and other physical hazards. Hazards associated with vehicle and pedestrian traffic in work areas and roadways were controlled by the use of warning signs, Men at Work signs, and road guards to direct traffic.

4.2.2 Personal Protective Equipment

PPE visions were made to minimize exposure to lead contamination for personnel on site. Level D PPE included the following:

- Hard hat
- Safety glasses
- Steel-toed leather safety shoes/boots
- Poly tyvek coveralls
- Nylon booties (under) and Robar/Tingley boots (outer)
- Inner sample gloves, outer cloth or leather gloves

An action level of 15.0 mg/m3 of airborne lead, as determined by integrated sampling, was set by USACE to upgrade the level of PPE to Level C (including use of an air purifying respirator.) Air monitoring was performed for the duration of remedial activities to ensure proper PPE use.

4.3 SITE SAFETY

4.3.1 Accidents

Employee safety was OHM's first priority. After performing more than 157,454 man hours on this project, OHM personnel suffered no OSHA-recordable accidents or injures.

4.3.2 Preventative Measures

A number of measures were taken on site to prevent accidents and injures. Daily safety meeting were held to discuss hazards associated with upcoming work tasks; the use of specific tools and equipment; and other chemical, physical, and environmental hazards associated with site work. Task-specific hazard evaluations were performed each day at the work sites prior to the start of work.

Controls were used to eliminate the hazards associated with vehicle and pedestrian traffic near the work locations. Warning signs were posted and guards were used to direct traffic.

A heat stress prevention program was also instituted on site. Personnel heat stress monitoring was performed to prevent heat related illnesses during work in high ambient temperatures. Site workers= pulses, body temperatures, and blood pressures were taken before and after each break. Work-rest schedules were determined by the results of this monitoring in accordance with the LSSHP heat stress monitoring criteria.

Specific work/rest regimens were established at the start of every work day based on the specific work conditions for that day (temperatures, time of day, amount of sun or shade, etc.) Breaks were taken in shady areas as designated throughout the work shift. Personnel removed PPE and were given cool liquids to drink (e.g., juice, water). Visual observation by a designated safety official was used to identify individuals exhibiting symptoms of heat-related illness and to take the necessary actions.

4.4 EXPOSURE MONITORING

4.4.1 Methodology

Air monitoring was performed to determine the ambient levels of total suspended particulates generated during excavation and to determine total ambient lead exposure for site personnel and perimeter emissions. At the start of each work day, wind direction was used to determine the placement of sampling instruments on site.

Personnel and perimeter samples were taken to determine the levels of total lead in the air of the personal breathing zone and at the site perimeter. Lead samples were collected and analyzed using NIOSH Method 7300 and battery-operated air sampling pumps (Gillian or equivalent) fitted with 37-millimeter (mm) mixed cellulose ester (MCE) filters (0.8-micron pore diameter).

4.4.2 Perimeter Sampling

Three perimeter samples were taken daily over the course of the work shift. One sample was taken upwind of site operations and two were taken downwind. Perimeter samples were taken above ground levels (approximately 4 to 5 feet in height) to characterize the breathing zone and to prevent contamination due to foot traffic. The pump flowrate was calibrated and set at approximately 20 liters per minute for the duration of the task (about 8 hours.)

Samples were assigned identification numbers based on an established code. The analytical laboratory used was Environmetrics, 11401 Moog Drive, St. Louis, Missouri. Standard turnaround time for

sample results was 24 to 48 hours by facsimile; original data was then returned by mail.

4.4.3 Personnel Sampling

Personnel air samples for lead were taken for a respective number of employees performing intrusive activities within the exclusion zone (one employee from each job category; at least two employees per day per site). The samples were taken in the person's breathing zone for the duration of the day's shift. Samples were collected at the end of the work day and sent to the analytical laboratory for analysis of total lead. A blank sample was included in shipment.

4.4.4 Medical Monitoring

Personnel blood lead levels were determined prior to and after the completion of work for this project.

5.0 QUANTITY SUMMARY TABLE

Quantities of material were tracked for each lot or site remediated. Table 5.1 presents a summary of these totals.

DACA45-96-D-0014 D.O. 0005 Project 19531

QUANTITY SUMMARIES

Site	Special	Sod	CA-6	CA-7	Topsoil
Address	cu yd	sq yd	ton	ton	cu yd
				1	
	119.37	960	46.2	28.84	119.37
	89.12	420	44.75	14.6	14.75
	89.12	420	44.75	14.6	14.75
	301.42	1260		1	46.15
	319.25	840	54.8	26.7	79.98
	36.35	240	14.65		20.54
	77.70	600	57.95	,	41.06
	146.82	360	13.79	28.35	104.41
	103.31	420			70.03
	86.65	300	56.48	14.27	34.48
	137.88	360	40.55	26.95	23.37
	146.62	270	86.9	28.5	26.66
	106.55	240	30.05	28.4	13.71
-	60.29	180			25.32
-	100.40	240	39.6		
	152.97	480	72.35	21.98	47.22
	124.53	420	42.3	21.63	33.35
	50.78	180	12.8	14.07	40.45
	64.76	210	14.65	14.3	31.48
	35.76	150	29.65	31	23.08
	63.92	180	31.15	44.8	39.22
	25.14	120		14.9	21.54
	26.25	120	1.	14.8	9.23
	60.64		32.55	46.7	
-	46.68	120	16.45	16.6	12.31
	32.00	452		<u> </u>	49.03
	33.64	150	17.5		11.34
	51.28	240	26.3	14.6	27.72
	50.85	240	42.09		59.40
	37.82	240		15.45	34.95
	30.82	180		1	34.08
	58.43	300	29.05	16.7	12.01

8.02 360 27.65 29.6 18.35 34.24 360 59.38 23.18 120 28.9 47.48 23.18 120 18.9 47.48 60.92 510 57.16 47.88 300 28.3 45.77 80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 15.3 123.86 660 76.59 52.57 32.16 150 74.45 16.25 127.22 180 28.35 69.39
34.24 360 59.38 23.18 120 28.9 47.48 23.18 120 18.9 47.48 60.92 510 57.16 47.88 300 28.3 45.77 80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 15.3 123.86 660 76.59 52.57 32.16 150 74.45 16.25
23.18 120 28.9 47.48 23.18 120 18.9 47.48 60.92 510 57.16 47.88 300 28.3 45.77 80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 74.45 16.25
23.18 120 18.9 47.48 60.92 510 57.16 47.88 300 28.3 45.77 80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
60.92 510 57.16 47.88 300 28.3 45.77 80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
47.88 300 28.3 45.77 80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 74.45 16.25
118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 74.45 16.25
94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
94.02 240 11.93 72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
72.66 420 57.18 47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
47.75 180 12.31 29.89 180 15.3 123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
123.86 660 76.59 52.57 32.16 150 17.55 39.55 150 74.45 16.25
32.16 150 17.55 39.55 150 74.45 16.25
39.55 150 74.45 16.25
127.22 180 28.35 69.39
126.71 444 29.3 14.5 116.52
57.18 317 14.35 13.95 48.67
96.49 378 13.5 24.52
64.65 444.5 14.8 57.59
42.25 190.5 23.35
229.48 540 76.55 25.35 83.12
82.88 240 44.4 14.6 32.31
46.77 360 45.27
42.31 360 30.5 27.1
49.51 300 14.5
30.78 60 30.4 13.33
33.17 420 14.55 14.65 23.65
31.80 120 23.08
68.25 180 16.15 12.85
46.71 240 14.77 13.8 24.03
94.72 180 14.65 44.5 47.69
107.87 189 90.05 27.46 21.08
145.12 300 55.35 125.38
118.38 240 45.33 25.55 54.68

138.04 508 30.55 82.58 159.33 420 58.9 90.5 24.62 137.65 283.5 73.09 14.7 36.73 161.02 120 16.98 34.77 54.33 218.25 1200 28.15 14.7 74.95 181.56 477 149.3 13.95 36.55 126.25 189 83.9 29.15 49.86 75.35 240 27.3 40.77 122.98 510 32.91 89.48 300 12.85 36.55 75.70 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 34.27 19.11 42.60 69.46 540 70.94 360 178.88 900 14.9 92.42 104.49 420 21.82 13.5 21.72 65.64 180 10.88 13.6 37.51 252 28.33 38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 57.50 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.15 34.68 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 59.48 53.68 81.54 350 34.68	•	1				
159.33 420 58.9 90.5 24.82 137.65 283.5 73.09 14.7 36.73 161.02 120 16.98 34.77 54.33 218.25 1200 28.15 14.7 74.95 181.56 477 149.3 13.95 36.55 126.25 189 83.9 29.15 49.86 75.35 240 27.3 40.77 122.98 510 32.91 89.48 300 12.85 36.55 75.70 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 178.88 90 14.9 92.42 104.49 420 21.82 13.5 21.72 65.64 180 10.98 10.98 110.88 126 73.8 13.6	•	•		,		
159.33 420 58.9 90.5 24.82 137.65 283.5 73.09 14.7 36.73 161.02 120 16.98 34.77 54.33 218.25 1200 28.15 14.7 74.95 181.56 477 149.3 13.95 36.55 126.25 189 83.9 29.15 49.86 75.35 240 27.3 40.77 122.98 510 32.91 89.48 300 12.85 36.55 75.70 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 178.88 90 14.9 92.42 104.49 420 21.82 13.5 21.72 65.64 180 10.98 10.98 110.88 126 73.8 13.6	(138 04	508	30.55	T	82 58
137.65 283.5 73.09 14.7 36.73 161.02 120 16.98 34.77 54.33 218.25 1200 28.15 14.7 74.95 181.56 477 149.3 13.95 36.55 126.25 189 83.9 29.15 49.86 75.35 240 27.3 40.77 122.98 510 32.91 89.48 300 12.85 36.55 36.55 75.70 420 15.05 33.89 111.78 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 35.44 51.50 36.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 540 540 540 70.94 360 14.9 92.42 104.49	-				90.5	
161.02 120 16.98 34.77 54.33 218.25 1200 28.15 14.7 74.95 181.56 477 149.3 13.95 36.55 126.25 189 83.9 29.15 49.86 75.35 240 27.3 40.77 122.98 510 32.91 89.48 300 12.85 36.55 75.70 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 104.49 420 21.82 13.5 21.72 65.64 180 10.98 13.6 10.98 10.98 10.98 13.6 10.98 110.88 126 73.8 13.6 28.33 36.46 60.79 1						
218.25 1200 28.15 14.7 74.95 181.56 477 149.3 13.95 36.55 126.25 189 83.9 29.15 49.86 75.35 240 27.3 40.77 122.98 510 32.91 89.48 300 12.85 36.55 75.70 420 15.05 33.89 111.78 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 70.94 360 14.9 92.42 104.49 420 21.82 13.5 21.72 65.64 180 10.98 110.88 126 73.8 13.6 37.51 252 2 28.33 3.92 126.12 420 15.15 29.8	7					
181.56 477 149.3 13.95 36.55 126.25 189 83.9 29.15 49.86 75.35 240 27.3 40.77 122.98 510 32.91 89.48 300 12.85 36.55 75.70 420 15.05 33.89 111.78 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 54.60 55.60 55.60 55.60 55.60 55.60 55						
126.25 189 83.9 29.15 49.86 75.35 240 27.3 40.77 122.98 510 32.91 89.48 300 12.85 36.55 75.70 420 15.05 33.89 111.78 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 540 70.94 360 36.21 36.22 3	-					1 1
75.35 240 27.3 40.77 122.98 510 32.91 89.48 300 12.85 36.55 75.70 420 15.95 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540						
122.98 510 32.91 89.48 300 12.85 36.55 75.70 420 15.95 33.89 111.78 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540					23.10	
89.48 300 12.85 36.55 75.70 420 15.05 33.89 111.78 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 542	-			27.0		
75.70 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540<				 	12.85	
111.78 420 15.9 23.07 96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 542	-					
96.57 480 14.75 83.78 47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 542 <td></td> <td></td> <td></td> <td>15.9</td> <td>10.00</td> <td></td>				15.9	10.00	
47.63 320 39.07 66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 540 540 70.94 360	-			4		
66.82 420 35.44 51.50 46.37 180 12.32 123.05 180 34.27 19.11 42.60 69.46 540 <td< td=""><td></td><td>· · · · · · · · · · · · · · · · · · ·</td><td></td><td>14.70</td><td>- </td><td></td></td<>		· · · · · · · · · · · · · · · · · · ·		14.70	- 	
46.37 180 34.27 19.11 42.60 69.46 540 70.94 360				35.44	- -	·
123.05 180 34.27 19.11 42.60 69.46 540 540 90 14.9 92.42 178.88 900 14.9 92.42 104.49 420 21.82 13.5 21.72 65.64 180 10.98 10.98 110.88 126 73.8 13.6 28.33 38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 24.62 25.33 34.41 95.55 240 54.3 20.15 21.85 34.41 95.55 240 54.3 20.15 21.85 34.41 95.55 240 54.3 20.15 21.85 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4 220.4 220.4 220.4 220.4 220.4 220.4	_				12 32	31.50
69.46 540 70.94 360 178.88 900 14.9 92.42 104.49 420 21.82 13.5 21.72 65.64 180 10.98 110.88 126 73.8 13.6 37.51 252 28.33 38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4	-			34 27		42.60
70.94 360 178.88 900 14.9 92.42 104.49 420 21.82 13.5 21.72 65.64 180 10.98 110.88 126 73.8 13.6 37.51 252 28.33 38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4			<u> </u>	· · · · · · · · · · · · · · · · ·		72.00
178.88 900 14.9 92.42 104.49 420 21.82 13.5 21.72 65.64 180 10.98 110.88 126 73.8 13.6 37.51 252 28.33 38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4				 		-
104.49 420 21.82 13.5 21.72 65.64 180 10.98 110.88 126 73.8 13.6 37.51 252 28.33 38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4 220.4					14.9	92 42
65.64 180 10.98 110.88 126 73.8 13.6 37.51 252 28.33 38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4				21.82		4 .
110.88 126 73.8 13.6 37.51 252 28.33 38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4					10.0	
37.51 252 28.33 38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 10.92 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4	_			73.8	13.6	10.00
38.96 300 36.46 60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4	-					28 33
60.79 190.5 59.2 15.5 33.92 126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4	- -			 	 	
126.12 420 15.15 29.8 23.07 85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4			<u> </u>	59.2	15.5	1
85.12 180 46.75 24.62 51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4 220.4	-		420			
51.30 381 34.41 95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4 220.4		85.12	180			
95.55 240 54.3 20.15 21.85 71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4		51.30	381			
71.80 317.5 13.75 32.95 86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4				54.3	20.15	
86.38 635 34.49 87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4						
87.18 300 10.92 83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4			635	1		
83.60 190.5 73.65 14.05 30.28 37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4		 			<u> </u>	
37.95 318 15 15 13.73 74.04 572 69.44 243.87 120 220.4				73.65	14.05	
74.04 572 69.44 243.87 120 220.4						
243.87 120 220.4			1		1	
~ 				220.4		
		81.54	350			34.68

		(
35.94	180		13.95		T
57.38	420	15.1	15.2	57.55	\top
55.72	254	14.45	15.2	24.78	\top
95.18	300		<u> </u>	60.26	+
55.68	286	· · · · · · · · · · · · · · · · · · ·		47.23	+
63.88	390	30.15		11.22	+-
58.39	480	32.15		34.92	+-
193.93	480	59.26	15	79.39	1
119.75	390			76.59	1
152.95	480	83.45		20.11	+
53.84	317.5	16.7	15.2	36.61	1
300.91	780	70.05	13.25	56.48	
101.58	480	30.9	12.91	30.00	+
45.35	254			33.11	T -
45.36	444.5			46.15	†
83.99	180	14.05	<u> </u>	11.03	1
40.63	240			9.45	1
40.25	300			45.34	T
27.35	317.5	14.95	14.3	22.42	†
32.23	240		13.7	11.25	1
42.20	100	72.55			\top
99.85	700	53.25			1
49.70	300	29.73			T
43.59	240	29.1			1
66.32	300	29.58	15.27		1
111.37	420	74.65	14.85		
65.72	240	15,45	14.8	34.94	
114.41	360		7		1
121.91	210	61.4	27	36.59	
79.15	240	17.3		40.39	1
48.85	350	12.55	29.35	12.37	1
60.02	434				Ι
89.81	420	13.5	31.39	56.57	
63.29	600			35.75	
75.15	420	15.8			T
64.45	240	15	15.05		
69.78	480	27.86			
92.55	540	15.65	14.85	56.27	

.

1			(
\	89.67	300	29.65	14.5	29.88
	33.65	240	15	15.05	
	108.07	500	43.77		
	46.90	300	43.77		34.42
	111.87	550	15.85	15.1	
	42.39	420	12.48	14.56	19.35
	39.81	190.5	15.6		31.68
	50.92	360	15.45	15.35	6.15
	88.24	222.5	44.8	14.9	47.82
	112.90	360	14.33	1	17.02
	23.24	120		14.3	13.19
	115.13	360	28.95		1
	52.01	180	23.87		21.55
	47.19	240	14.7		7.50
	53.58	120			
	51.81	360	14.35		23.27
	124.67	120'	13.9	13.7	51.68
	82.06	320	29.75		11.58
	64.86	222.5	20:10	15.4	12.82
	107.93	180	148.05	31.4	
	88.75	120	88.1	14.15	
	63.72	480			
	25.51	240	13.9	13.2	18.15
	104.69	180	86.74	13.52	10.10
	46.75	180	15.37	13.25	
	60.65	180	29.85	14.75	
	53.23	240	26.85	14.15	
	64.19	420			23.08
	53.82	378	53.2	16	
	55.10	330	14.1	1	1
	50.93	260	34.6		
	102.15	240	15.55	 	9.17
	96.55	360	59.45	14.55	12.25
	76.68	480	30.95		11.55
	69.27	240	15.1		12.42
	79.23	480	27.55	13.45	
	91.91	300	<u> </u>	30.6	35.52
	102.46	480	29.6	13.8	

,

		•			·
		,			
	28.78	120		14.35	
	74.24	360	38.35	14	
	89.37	420	12.65		
	65.76	378	41.95	12.95	
	49.47	300	58.41		11.07
	48.89	300	26.5	14.4	
	127.06	400		13.75	20.05
	131.88	360		13.75	34.04
	74.92	360	14.95		22.12
	48.71	180			23.01
	94.38	360		14.85	34.42
	40.04	120	13.3	:	
	67.95	180	15.35	29.3	23.54
	284.94	1260	14.8	15.05	41.72
	52.79	300	43.6	26.5	24.12
	41.22	180			24.63
	34.84	240			26.86
-	53.38	240			21.90
	20.99	210			11.37
	131.53	450	59.3	14.9	11.69
	189.40	952.5			56.76
	118.01	540			58.17
	26.88	127		15.1	12.08
	29.47	254			38.12
	194.72	347	74.55	14.9	83.48
	75.55	120		13.9	26.52
	117.64	317.5	43.95	14.45	37.14
	47.32	159		14.95	11.79
· · · · · · · · · · · · · · · · · · ·	92.17	300	11.95	14.65	25.32
	96.50	635			104.62
	48.63	254			25.04
	35.73	441		13.5	40.00
	26.59	127		14.25	23.64
	335.79	1323		43.4	183.03
	204.97	850.5		28.45	271.45
	79.72	220.5	13.95	13.95	23.74
	98.74	346.5	40.8	 	23.74
	83.47	381		49.75	38.37

67.15 381 31.9 49.43 68.54 360 28.75 54.18 100.05 540 13.2 38.74 35.78 157.5 29.5 22.69 16.62 60 14.95 18.72 11.54 189.72 30 358.75 11.54 15.4 58.58 180 10.92 11.91 11.91 45.90 180 10.92 11.91 11.91 27.23 63 10.92 30.35 122.98 444.5 14.8 36.62 140.36 190.5 153.2 14 41.28 16.2 74.90 300 11.62 15.15 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23 80.42 60 15.25 30.25	
100.05 540 13.2 38.74 35.78 157.5 29.5 22.69 16.62 60 14.95 11.54 189.72 30 358.75 11.54 58.58 180 10.92 11.91 45.90 180 10.92 11.91 27.23 63 10.92 12.98 249.69 945 14.69 58.66 93.35 122.98 444.5 14.8 36.62 140.36 190.5 153.2 14 41.28 74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	
35.78 157.5 29.5 22.69 16.62 60 14.95 11.54 189.72 30 358.75 11.54 58.58 180 10.92 11.91 45.90 180 27.23 63 10.92 249.69 945 14.69 58.66 93.35 122.98 444.5 14.8 36.62 140.36 190.5 153.2 14 41.28 74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	Γ
16.62 60 14.95 189.72 30 358.75 11.54 58.58 180 10.92 11.91 45.90 180 27.23 63 10.92 249.69 945 14.69 58.66 93.35 122.98 444.5 14.8 36.62 140.36 190.5 153.2 14 41.28 74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	Π
189.72 30 358.75 11.54 58.58 180 10.92 11.91 45.90 180 27.23 63 10.92 249.69 945 14.69 58.66 93.35 122.98 444.5 14.8 36.62 140.36 190.5 153.2 14 41.28 74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	Π
58.58 180 10.92 11.91 45.90 180 10.92 11.91 27.23 63 10.92 1249.69 945 14.69 58.66 93.35 122.98 444.5 14.8 36.62 36.62 140.36 190.5 153.2 14 41.28 74.90 300 11.62 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	Γ
45.90 180 27.23 63 10.92 249.69 945 14.69 58.66 93.35 122.98 444.5 14.8 36.62 140.36 190.5 153.2 14 41.28 74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	Γ
27.23 63 10.92 249.69 945 14.69 58.66 93.35 122.98 444.5 14.8 36.62 140.36 190.5 153.2 14 41.28 74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	Π
249.69 945 14.69 58.66 93.35 122.98 444.5 14.8 36.62 140.36 190.5 153.2 14 41.28 74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	Π
122.98 444.5 14.8 36.62 140.36 190.5 153.2 14 41.28 74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	
140.36 190.5 153.2 14 41.28 74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	Π
74.90 300 11.62 47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	
47.22 180 16.4 13.85 16.38 41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	Г
41.24 423 15.15 12.12 43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	
43.28 164 30.15 45.65 11.05 150.12 63 104.97 73.4 9.23	\Box
150.12 63 104.97 73.4 9.23	
	Γ
80.42 60 15.25 30.25	Г
	Γ
96.57 360 71.85	Γ
101.93 180 70.4 13.1	Γ
91.05 420	Г
36.39 180 41.7	$ ag{}$
48.75 480 43.8 16.9	Γ
72.50 310 60.85 14.2	T
130.37 300 13.6 27.65	\vdash
49.62 180 43.45 13.85	Γ
50.88 360 29.2 14.2	
64.99 300	\Box
160.73 1140 14.6 108.32	Γ
78.13 420 13.4 23.95 38.48	T
152.45 660 61.7 51.8 54.86	Γ
58.76 180 28.13	Γ
50.95 180 15.3 38.93	T
88.62 540 44.89	T
71.04 300 33.78	\top
41.85 180	\top
59.79 300 14.1 22.50	\top
86.11 120 28.1 14.2	1

28.82	240	13.1		19.54
163.05	315		29.1	
102.63	420	29.05	14.35	22.30
97.19	300	73.21		58.01
43.35	420	1		24.51
161.67	360	117.03	31.4	10.23
156.80	900	1.7.35	15.2	55.06
42.13	240	14.59	13.1	1 00:50
19.45	120	1		
86.93	240	82.9	13.35	16.79
52.71	240		31.7	23.58
51.62	360	29.41		
25.63	180			
92.32	360	·	12.85	67.65
191.80	1200	28.15	12.00	<u> </u>
149.15	420	20.10	14.1	13.91
83.22	700		7.5	10.01
44.87	180	58.05	12.85	10.71
137.43	81	91.66	12.50	21.59
58.39	240	31.00	<u> </u>	24.02
64.87	300			24.02
114.18	600			18.84
145.75	900	25.35		21.54
120.40	300	13.2		33.65
155.65	420	70.24	30.22	
275.60	780	1	15.45	1
62.92	540	13.45	13.8	47.42
41.16	300	13.9		†
65.94	480	1		22.48
95.61	300	44.85	15.3	22.34
102.88	506			1.
97.34	667	14.5	13.55	66.88
62.47	120	29.9	15.3	16.25
113.52	480		14.75	40.36
130.02	600			56.28
30.42	32	29.5	14.8	12.08
77.97	60	44.5		9.35
52.60	360	 		23.02

	,				
((
	92.53	600	16.05		52.23
	89.72	360		15.6	39.56
	44.10	480			37.34
	70.72	360		14.25	49.45
	83.67	540	14.65	13.25	21.85
	163.90	157.5	57.2	41.3	25.31
	251.45	504	87.3	43.5	105.32
	62.10	190.5	29	14.15	35.78
	91.71	252	15.2	13.9	45.67
	87.73	540	15.85	14.8	22.47
	57.75	360		35.35	25.31
	55.74	420		7.95	36.15
	63.55	360			20.42
	57.04	240	14.6		11.55
	44.56	300	14.5	15.05	12.90
	36.74	240		14.25	11.74
	88.24	240		14.65	51.02
	139.20	603	28.1	14.2	29.82
	95.58	189	73.7		26.09
	108.92	254	14.65	15.9	23.68
	66.08	254	44.74	16.4	14.46
	67.22	222	13.95	26	12.88
	26.67	222			25.38
	54.97	254		28.05	47.39
	36.04	286		14.35	47.58
	59.42	180	<u></u>	14.9	23.85
	33.19	300	14	13.05	10.24
·	65.25	381		14.25	40.69
	116.68	560	14.7	14.55	23.52
	61.12	480	14.85	14.9	23.38
	87.07	570	17.1		32.85
	138.58	317.5	72.7	14.66	26.46
	79.80	360	26.85		33.08
	52.05	420		14.35	9.90
	67.62	300	14.85		21.24
	40.84	240	<u> </u>		10.78
	41.07	240	 	<u> </u>	12.00
	43.04	330	<u> </u>	<u> </u>	11.48

					,
		•			
<u> </u>	· · · · · · · · · · · · · · · · · · ·				
	105.38	150	40.4	13.5	12.18
	93.08	240	60.6	14.4 ~	21.59
	78.62	240	69.74	14.8	20.79
	43.23	180		12.45	42.08
	26.04	180	13.8	13.65	21.73
	99.32	270	14.95	27.3	42.58
	140.03	240	91.05	89.55	24.35
	135.85	254	43.52	15.64	51.42
	24.24	95	17.65		26.00
	21.49	63.5			
	18.75	95	32.25		13.85
	34.82	127	15.9		
	46.52	360		14.8	21.39
	61.32	420	66.8	14.9	
	183.12	240	88.6	13.9	41.77
	306.46	60	507.75	58.85	12.31
	261.01	300	79.6	16.8	
	250.16	60	317.1	29.9	
	35.58	120			
	205.52		259.45	90.55	
	78.85		120.3	60.65	
	130.51	360	57.65	14.3	25.35
	216.50	189	239.02	26.22	20.17
	68.07	480	46.6		36.92
	153.53	252	63.1	14.05	35.32
	86.68	220.5	28.5	70.84	54.49
	38.49	120	12.52	13.59	
	63.36	381		12.14	35.05
	180.50	540	28		53.44
	67.98	. 189	28.7	13.8	10.99
	186.42	409.5	87.6	14.55	63.52
	158.61	189	325.5	15	11.54
	90.70	285.5	29.65		28.56
	49.44	63	14.5	13.8	35.66
	191.59	840	13.95		82.91
	52.92	472.5			44.55
	117.09	317.5	15	29.6	41.60
	53.21	360	13.55		11.90
					

.

		1		
83.66	254	15.55		35.25
141.47	420			32.55
46.01	420	12.75		45.37
52.46	286		29.35	51.28
57.09	508			76.68
44.52	381		14.85	53.84
42.85	190.5		15.2	36.18
199.41	693	28.85	15.2	71.98
87.14	480	27.94	14.7	
140.64	540	36.88	7.5	
91.48	600	32.45	,	
72.12	480	30.15	,	
149.87	660	26.6	29.05	79.89
81.57	508	27.55	13.9	39.92
62.04	240			12.27
245.41	700	118.2		63.30
222.07	1620	102.5	28.05	180.46
229.71	1920			
394.43	1080	28.2		156.02
84.12	378	44.2	14.8	38.62
386.50	, 4740	40.7		412.37
77.82	315	15.45	29	35.75
128.56	126	166.22	62.57	23.32
162.43	507	33.15	13.6	111.28
96.36			14.35	105.08
79.95	441	29.05	30.7	70.55
155.97	600			38.36
47.78	344			60.63
135.60	375	96.45	50.5	56.92
25.11	159	15.45	15.15	46.43
122.31	315	100.86		67.74
33.02	150		28.45	11.62
59.09		75.2		
67.74	720	44.65	13.7	
16.83	127			10.91
71.43	378		12.83	11.11
117.27	252	15.37	13.6	45.68
138.80	698.5	18.7	15.35	46.65

		•			
109.22	381	14.95	13.6	28.37	T
55.26	94	30.6			1
55.66	188	14.9	41.91	10.77	1
73.14	189			46.15	\top
56.28	190.5	15.05	- 15.55	11.69	\top
82.18	159	18.7	15.35	46.65	\top
317.66	. 990		13.85	216.56	
49.99	120	14.7		11.94	
219.76	180	177.92		12.02	\top
137.55	444.5	14.6	30.4	135.72	+
124.82	819		15.15	19.75	+-
113.32	480	14.85			+-
123.64	360	120.02		54.62	\top
160.70	381	81.65	14.35	22.54	1
114.11	420	30.45	14.2	12.53	\top
70.40	420	29.95	14.4	10.53	1
50.73	420			10.57	
336.42	1920	42.3	16.3	88.20	1
180.39	360	82.37		21.86	1
172.12	420	92.1	32.15	92.99	1
33.44	240		15.1	12.46	\top
25.35	120			13.31	\top
146.70	360	44.15	14.85	40.65	\top
71.65	189	29.15	30.3	34.24	7
211.52		268.65	30.3		1
266.93		174.9	30.3		1
185.40	·	221.05			1
102.05	31.5	133.2		3.08	\top
65.87		97.15	69.5		T
64.23		85.55	27.8		\top
111.55		164			\top
109.94	420	57.4	27.45	17.34	1
164.45	1200	21.85			1
79.57	420				十
94.92	240	27.7	13.9		1
76.36	300			9.34	1
61.73	360	42.7		6.15	T
31.25	180	15.23			\top

					•
•			(
	103.95	540	44	15.1	T
	191.02	420	14.15	15.05	
	52.38	180	26.4	14.15	
	34.78	240	14.2		
	80.93	180	13.05	15.25	
	58.98	360	14.65		
	50.47	480	28.25	12:4	
	116.52	300			
	56.35	120	,	13.1	
	12.99	180			23.65
	19.92	240	1	 	56.68
	68.02	450	29.1	15	1
	78.04	504	14.95		
	67.05	189	28.75	12.6	†
	29.96	240	15.5		
	26.58	180	15.1	13.9	
	35.91	180			12.48
	88.46	540			38.87
	172.48	800			95.38
	229.05	540	31.65	15.55	349.75
	76.92	190.5	49.05	15.1	25.09
	72.55	159	31.85		34.79
	17.48	126			
	61.18	180	13.15		26.49
	38.30	240	12.15		18.10
	123.90	283.5	13.95	27.7	62.38
	201.25	1079.5		40.2	197.93
	142.83	378	35.6	29.75	41.95
	43.70	180	·	29.75	9.83
	95.74	254	43.75	15.35	13.40
	102.93	252	30.36	29.75	22.63
	58.40	222	43.35	14.05	13.69
	59.75	240	15.4	15.25	13.92
	55.20	240	14.25		15.32
	25.40	60			4.38
	56.87	300	14.26		25.08
	47.74	150	31.9	15.65	10.98
	117.78	330	74.26		45.04

.

T - 4 - 1 -	45070 40	475405.00	45404.00	C427.00	44005.00
	32.69	60	29.5	16.85	
	43.11	120	15	13.45	
	26.95	. 60	32.85	15	
	38.10	180	41.5	14.15	
	136.00	254	57.95	59.35	94.80
	126.86	570	43.32		12.15
	61.39	190.5	31.85		13.45
	43.45	120	35.15		21.45
	234.97	889	29.05		165.61
	46.78	360	13.95	12.55	
	82.38	300		14.6	
	56.98	320		14.05	24.22

Total:

45278.42

175405.00

15194.36

6127.98

14865.06

6.0 VERIFICATION ANALYTICAL SUMMARY TABLE

6.1 Stack Emission Sites

Stack emission sites were not sampled for verification. This was due to the fact that a predetermined depth for excavation was given to OHM by USACE for each stack emission site.

Stack emission sites are sampled for pre-characterization analysis. Depth's from Woodward/Clyde Sampling are being reviewed by the USEPA and may result in re-sampling.

7.0 PHOTO REPRESENTATION

Photographs and videocassettes documented all sites in all phases of the Granite City project. Each property was documented with before, during, and after photographs and videos. The following sections are representative of the various types of work performed during Phases 1, 2, and 3. Not all properties - only selected representative samples - are presented in this final report, in order to minimize the volume of paper.

2222 Cleveland (Page 7-2)

Top picture – Lot before excavation Middle picture – Lot during excavation Bottom picture – Lot after restoration/sod

1703 Elizabeth (Page 7-3)

Top picture – Lot before excavation Middle picture – Lot during excavation Bottom picture – Lot after restoration/sod


1231 Iowa (Page 7-4)

Top picture – Lot before excavation

Middle picture – Lot during excavation

Bottom picture – Lot after restoration/sod










APPENDIX A

FLOW CHARTS


APPENDIX A-1	OPERATIONS FLOW CHART
APPENDIX A-2	TECHNICAL EFFORT FOR TRANSPORTATION AND
	DISPOSAL
APPENDIX A-3	TECHNICAL EFFORT FOR SAMPLING
APPENDIX A-4	SITE COORDINATOR FLOW CHART

OPERATIONS FLOW CHART




A-1


TECHNICAL EFFORT FOR TRANSPORTATION AND DISPOSAL



TECHNICAL EFFORT FOR SAMPLING




SITE COORDINATOR FLOW CHART



A-5

APPENDIX B - REMEDIAL LOCATION WORK DESCRIPTIONS



USACE Granite City, Illinois ©1998 OHM Remediation Services Corp. Project No. 19531 Final Report October 16, 1998 Action Date: 6/24/97 Loadout: 6/25/97

Restoration Begins: 6/26/97 Restoration Completed: 7/12/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 113.96 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Keeven sod farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

SPECIAL WASTE	BACKFILL TOPSOI	L CA-6	CA-7	SAND SOD	CONCF
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS) CU.YDS	3.
155.18	268.27	46.2	28.84	960	

Sampling Analysis
Project #19531

0 - 3" Front and Back

	0 - 0	I TOTIL CI	Id Dack
	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

		000.
С	C	С
PPM	PPM	PPM
No.	No.	No.

590


580

418

63

193

40



.

•

Action Date: 12/8/97

Loadout: 12/8/97

Restoration Begins: 12/11/97 Restoration Completed: 12/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 101.13 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26


*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

QUANTITY SUMMARY FOR



Sampling malysis
Project #19531


0 - 3" Front and Back

	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


J - U	i ioni ai	id Dack
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

X = SAMPLE POINT



Action Date: 7/17/97

Loadout: 7/17/97

Restoration Begins: 7/21/97 Restoration Completed: 8/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 89.12 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

- *WMI-landfill
- *B. Garcia-trucking
- *Granthum-trucking
- *Schneider Turf Farm

QUANTITY SUMMARY FOR

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS.	
115.86	6.	19.18	44.75	14.6	420	

Sampling hallysis Project #19531

0 - 3" Front and Back

			10 5001
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6" Front and Back
B B B
PPM PPM PPM
No. No. No.

6 - 12" Front and Back
C C C
PPM PPM PPM
No. No. No.


530 353 361 **600**


558 280 259 **577**

915 25145 223324 349



X = SAMPLE POINT





Restoration Begins: 4/24/98 Restoration Completed: 5/14/98

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 301.14 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Schneider-turf farm

QUANTITY SUMMARY FOR

BACKFILL

(LOADS)


35

60

SPECIAL WASTE

(TONS)


391.84




1260

Sampling Analysis Project #19531

Street/Number Address



3-6" Front and Back		6-12" Front a			
B PPM No.	B PPM No.	B PPM No.	C PPM No.	C PPM No.	
223	217		183	119	
133	8398		87	7043	
101	668		158	536	



Action Date: 10/16/97

Loadout: 10/20/97

Restoration Begins: 10/20/97 Restoration Completed: 11/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 319.25 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	· (LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>
415.03	15	103.98	54.8	26.7		840	

Sampling Analysis Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

586

872


436

882

236

843

519 65



B1 15' from bor 12' from 3.dewalk

32 10' from Shid 12' from PP Action Date: 9/16/97

Loadout: 9/18/97

Restoration Begins: 9/23/97 Restoration Completed: 10/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 36.34 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
_	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>
	47.25		26.7	14.65			240	

Sampling Analysis Project #19531

0 - 3" Front and Back

	0 - 3	i i Olit ai	IG Dack
	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

0 0		id Duoi
В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back

•		
С	C	С
PPM	PPM	PPM
No.	No.	No.

0100110

135 **538** 471 182 245 208 97 99

9 108



Action Date: 9/18/97 Loadout: 9/20/97

Restoration Begins: 9/20/97 Restoration Completed: 10/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 77.70 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

- *WMI-landfill
- *B. Garcia-trucking
- *Granthum-trucking
- *Emerald Turf Farm

QUANTITY SUMMARY FOR

SPECIAL WASTE

(TONS) 101.01

·						
BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCE
(LOADS)	(TONS)	(TONS)	(TONS)	. (TONS)	CU.YDS.	<u>i</u>
5	53.38	57.95			600	

Sampling malysis
Project #19531

0 - 3" Front and Back

	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	· No.

6 - 12" Front and Back

		mile Duois
C	C	С
PPM	PPM	PPM
No.	No.	No.

268


914

198


670

29

634



A)2116 19-13-20-401-013 WTBO
-E/2110 401-011 C07327
401-010 C0733. NO



Restoration Begins: 9/26/97 Restoration Completed: 10/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 146.81 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW


*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm



0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

184


6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.

241 339

240

154 **637** 239 **2031**





Action Date: 4/17/97 ∠Loadout: 4/17/97

Restoration Begins: 4/18/97 Restoration Completed: 5/14/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 103.30 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
134.3	8	91.04				420	

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

B	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

, O 12	I TOTAL	and Daoi		
С	C	C		
PPM	PPM	PPM		
No.	No.	No.		

639

715

1020


465


496 1080

454

717

436





Restoration Begins: 4/30/97 Restoration Completed: 5/15/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 86.65 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
112.65	7 .	44.82	56.48	14,27		300	

0 - 3" Front and Back

2650

	Α	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

547

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

No. No. 535 152

PPM

434 454 **623 1405**

488 **1071**


6 - 12" Front and Back C C C


PPM

No.

PPM

i





Restoration Begins: 10/15/97 Restoration Completed: 10/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 137.88 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2144/46 ADAMS

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
1	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
_	179.25	10	30.38	40.55	26.95		360	

0 - 3" Front and Back

	A	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

246 **556** 3000 1010

3 - 6" Front and Back


		1 10111 4	id Duoi
	В	В	В
ı	PPM	PPM	PPM
	No.	No.	No.


126 **606** 248 221 238 262

6 - 12" Front and Back

C	C	С
PPM	PPM	PPM
No.	No.	No.

99 **506** 110 101 175 **529**





Restoration Begins: 5/19/97 Restoration Completed: 6/2/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 146.62 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm


EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

(LOADS)

(TONS) 190.61



270

28.5

86.9

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

529 1460

3 - 6" Front and Back


	. <u> </u>	ie odori
В	В	В
PPM	PPM	PPM
No.	No.	No.

269 **1250** 234 240


6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.

68 **1290** 313 **5109**



X = SAMPLE POINT





Restoration Begins: 10/27/97 Restoration Completed: 11/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 106.55 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

ſ	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
. [(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
	138.52	8 .	17.82	30.05	28.4	1	240	

0 - 3" Front and Ba	ack	Ba	nd	ar	nt	ro	F	3"	_	0
---------------------	-----	----	----	----	----	----	---	----	---	---

	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

546 461

3 - 6	" Fr	ont	and	Back.
-------	------	-----	-----	-------


В	В	В
PPM	PPM	PPM
No.	No.	No.


658 151 **602** 323

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

651 116 404 158





Restoration Begins: 10/27/97 Restoration Completed: 11/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 60.29 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u>'</u>
78.38	6	32.91				180	

0 - 3" Front and Back

	- <u>A</u>	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

	1 10111 4	id Dadi
В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back

C	С	С
PPM	PPM	PPM
No.	No.	No.

1040 570

1044 622

371 **815** 390 429



Action Date: 3/30/98 Loadout: 4/2/98

Restoration Begins: 4/2/98

Restoration Completed: 4/18/98

*Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.

- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 100.40 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

TCM

*X331

*17-KW

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Grantham-trucking
 - *Schneider Turf Farm



SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
130.52	8		39.6	. ,		240	

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

290	379
178	505
249	735


3 - 6" Front and Back		
В	В	В
PPM	PPM	PPM
No.	No.	No.


164	324
107	612
116	730

6 -	12"	Front	and	Back
-----	-----	--------------	-----	------

С	С	C
PPM	PPM	PPM
No.	No.	No.

48	239
69	504
52	795





Restoration Begins: 10/27/97 Restoration Completed: 10/31/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 152.96 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCE
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>
198.86	10	61.39	72.35	21.98		480	

Sampling Analysis
Project #19531

0 - 3" Front and Back

	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back


J - U	I I OTTLE	id Dack
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back				
С	C	C		
PPM	PPM	PPM		
No.	No.	No.		


510 428


511 385510 256

598 224541 208



X = SAMPLE POINT





Restoration Begins: 10/28/97 Restoration Completed: 10/31/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 124.53 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

		•						
	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCE
:	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u>. </u>
-	161.89	. 5	43.36	42.3	21.63		420	!

Sampling analysis Project #19531

0 - 3" Front and Back

_,			12 5451
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

462 258303 397402 423


3 - 6" Front and Back


		id Davi
В	В	В
PPM	PPM	PPM
No.	No.	No.

310 474 237 141 353 **548** 6 - 12" Front and Back

	0 12	_ 1 1 0 1 1 1 2	and Duoi
	C	C	C
Γ	PPM	PPM	PPM
	No.	No.	No.

119 97 150 54 239 223





Restoration Begins: 7/16/97 Restoration Completed: 8/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 50.78 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND SOD	CONCF
(TONS)	(LOADS) : (TONS)	(TONS)	(TONS)	(TONS) CU.YDS.	
66.02	52.58	12.8	14.07	180	

Sampling Analysis Project #19531

0 - 3" Front and Back


1 .	Α	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back			
В	В	В	
PPM	PPM	PPM	
No	No	No	


6 - 12" Front and Back				
C C C				
PPM	PPM	PPM		
No.	No.	No.		


915 111 1201 880 255 176

143 299



X = SAMPLE POINT





Restoration Begins: 7/1/97 Restoration Completed: 7/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 64.76 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS	
84.19	. 5	40.93	14.65	14.3	210	

Sampling Analysis Project #19531

0 - 3" Front and Back

	0	1 10111 4	
	Α	Α	· A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


C	С	С
PPM	PPM	PPM
No.	No.	No.

1110

527 1210

128

437





Restoration Begins: 3/20/97 Restoration Completed: 3/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 35.76 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Petago Sod Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
46.49	1	30	29.65	31		150	

Sampling Analysis
Project #19531

0 - 3" Front and Back

		I IOIK GI	IG DGON
,	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


C	С	С
PPM	PPM	PPM
No.	No.	No.

577 128 467 248

337 209

182

44



Bi I'Not Walkway

21' Wot house

House & Paicment = 70%

BZ 17' Sol fonce 12' Wot Shed

20 /

Action Date: 6/5/97 ✓Loadout: 6/6/97

> Restoration Begins: 6/7/97 Restoration Completed: 6/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 63.92 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	_(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
83.1		50.98	31.15	44.8		180	

Sampling malysis Project #19531

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

798


1675

367


95

84

250



ی ک



Restoration Begins: 3/24/97 Restoration Completed: 4/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 25.13 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Roller

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedago Sod Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.



SPECIAL WASTE	BACKFILL TOPSOIL	CA-6 CA-7	SAND SO	D CONCRETE	OTHER
(TONS)	(LOADS) (TONS) ((TONS) (TONS)	(TONS) CU.Y	DS	· !
32.68	28	14.9	. 12)	

Sampling Analysis Project #19531

0 - 3" Front and Back

			. — — — — · · ·
	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

3-0	I I OI IL ai	id Dack
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.


639

686


300 . 335


53

117



X = SAMPLE POINT





Restoration Begins: 3/24/97 Restoration Completed: 4/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 26.24 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Roller

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Pedago Sod Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

i	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
L	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
Г	34.12		12		14.8		120	

Sampling Analysis Project #19531

0 - 3" Front and Back

·	O O I TOTIL GITG DOOK			
	_ A	Α	Α	
Street/Number	PPM	PPM	PPM	
Address	No.	No.	No.	

3 - 6" Front and Back
B B B
PPM PPM PPM

No.

Dack	
В	
PPM	
No.	

6 - 12" Front and Back
C C C
PPM PPM PPM

No.

No.

E


367 **709 513 736**

319 **521** 410 297


No.

216 364

No.



House & Paviment = 80%



Restoration Begins: 6/7/97 Restoration Completed: 6/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 60.63 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:
 - *TL-26
 - *17-KW
 - *X331
- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
78.83		32.55	46.7			

Sampling Analysis
Project #19531

Ω	- 3"	Front	and	Back

			id Daois
	. A	Α	· A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3	- 6"	Fro	nt and	d Back

0 0	i i Oiit ai	IG DGOIL
В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back

C.	C	С
PPM	PPM	PPM
No.	No.	No.


516 257 444


376 132

223



X = SAMPLE POINT





Restoration Begins: 4/3/97 Restoration Completed: 4/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 46.68 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Roller

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedago Sod Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SOD CONCE
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS.
60.69	2	16	16.45	16.6	120

Sampling malysis
Project #19531

0 - 3" Front and Back

	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


C	С	С
PPM	PPM	PPM
No.	No.	No.


550

651

903 616

624





Restoration Begins: 6/23/97 Restoration Completed: 7/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 32.00 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill


*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.



Sampling malysis Project #19531

0 - 3" Front and Back

	Ά	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.


626


916

335

347

116





Restoration Begins: 4/2/97

Restoration Completed: 4/10/97

*Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.

- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 33.63 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Kobotoa

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedago Sod Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u>: </u>
43.73		14.74	17.5	<u> </u>		150	:

Sampling Analysis
Project #19531

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back


		14 5451
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

C	С	C
PPM	PPM	PPM
No.	No.	No.


660 415

129 242



House & Parament = 90%

. Jak



Restoration Begins: 7/24/97 Restoration Completed: 8/20/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 51.27 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Roller

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SO	D CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.Y	DS
66.66	1	36.04	26.3	14.6	240	

Sampling malysis Project #19531

0 - 3" Front and Back

		I I OIII C	IG DUON
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

835 404 167 141 45



_



Restoration Begins: 3/28/97 Restoration Completed: 4/24/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 50.84 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*17-KW

*X331

*Subcontractors:

- *WMI-landfill
- *B. Garcia-trucking
- *Granthum-trucking
- *Pedago Sod Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
66.1	2	77.22	42.09			240	

Sampling Analysis Project #19531

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.

570 420

459 574



_



Restoration Begins: 10/8/97 Restoration Completed: 10/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 37.81 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW


*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm



Sampling hualysis Project #19531

0 - 3" Front and Back

	Α	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

188	312
49	91
846	222
107	216

3 - 6" Front and Back


	I IOIK GI	IG DOON
В	В	В
PPM	PPM	PPM
No.	No.	No.

256	246
678	163
491	185


6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.

82	361
49	51
50	107



X = SAMPLE POINT





Restoration Begins: 4/14/97 Restoration Completed: 4/25/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 30.82 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION


This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR-

44.3

SPECIAL WASTE

(TONS) 40.07



0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

404

6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.

185

520


877

257



BI I' E of wall il! S of force

BZ 7' wot shop 20'S of fine 60% Paved



Restoration Begins: 8/14/97 Restoration Completed: 8/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 58.43 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*Roller

17-1741

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SO	D CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.Y	DS.
75.96	3	15.61	29.05	16.7	300	0

0 - 3" Front and Back

	0 0		ia bacit
	Α	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back


0 0	i ionicai	id Duon
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.

474 470

557 310 **1055** 460



X = SAMPLE POINT



Action Date: 6/18/97 Loadout: 6/19/97

Restoration Begins: 6/19/97 Restoration Completed: 7/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 77.24 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
100.42	4	23.85	27.65	29.6		360	

0 - 3" Front and Back


	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back
B B B
PPM PPM PPM
No. No. No.

6 - 12" Front and Back
C C C
PPM PPM PPM
No. No. No.

168 **668** 85 447

184 573 154 **509**



X = SAMPLE POINT

52' X 129'

OHM Corporation
Findley Ohio

Drawn By
EDJ Checked By:
7/29/98 Approved By:

NTS Drawing No:

Action Date: 4/18/97 -Loadout: 4/25/97

Restoration Begins: 4/26/97 Restoration Completed: 5/12/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 34.23 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	:
44.51		77.19	· ·			360	

0 - 3	" From	nt and	l Back
-------	--------	--------	--------

	A	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6"	Front ar	nd Back
--------	----------	---------

	<u> </u>	<u> </u>
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 1	12"	Front	and	Back
-------	-----	-------	-----	------


С	С	С
PPM	PPM	PPM
No.	No.	No.

479

987

114 470

48



Action Date: 6/11/97

Loadout: 6/12/97

Restoration Begins: 6/12/97 Restoration Completed: 6/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 23.17 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6 CA-7	SAND	SOD	CONCI
(TONS)	(LOADS) (TONS)	(TONS) (TONS)	(TONS)	CU.YDS.	
30.13	61.73	.28.9		120	•

0 - 3" Front and Back

	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

0.0	I TOIL CI	ia Daoi
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


C	С	С
PPM	PPM	PPM
No.	No.	No.

611

1240

441 384

81




B1 3 to 5 dewark

House & Paved are = 70%

BZ ZO' to house ZE' tosForce

- NOK 1



Restoration Begins: 6/12/97 Restoration Completed: 6/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 20.30 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6 CA-7	SAND	SOD	CONCE
(TONS)	(LOADS) (TONS)	(TONS) (TONS)	(TONS)	CU.YDS.	
30.13	61.73	28.9	: 	120	

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

C	С	С
PPM	PPM	PPM
No.	No.	No.


520


447

244

317

43





Restoration Begins: 9/5/97 Restoration Completed: 9/12/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 60.91 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
79.19	74.31	9			510	_

0 - 3" Front and Back

693

	A	A	Α
Street/Number	PPM	PPM	PPM
Address	Ño.	No.	No.

476

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
· No.	No.	No.


190 404

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

696 85143 69120 261

E



BI 6' From Gronz Wall

1 8' from walk into horse

BZ 9' to N fence

Zs' to shed

Horse : Pavement = 60%

48 St de

Action Date: 9/5/97

Loadout: 9/8/97

(

Restoration Begins: 9/8/97 Restoration Completed: 9/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 47.88 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

SPECIAL WASTE	BACKFILL TOPSOI	L CA-6 CA-7	SAND SOD	CONCI
(TONS)	(LOADS) (TONS)	(TONS) (TONS)	(TONS) CU.YDS.	
62.25	49.5	28.3	300	

Λ.	- איי	Fro	nt :	and	l Rs	ack
· ·					uc	\sim

	Α	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 -	6"	F	ror	ηt	and	Back

J - U	1 TOTIL GI	d Daoi
В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

 558
 377


 461
 286

265 409



B'- 8' no. th of house is 4' east of deriver of house.

Bir 16' west of ched of 24' - .. 1



Restoration Begins: 5/5/97

Restoration Completed: 5/16/97

*Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.

- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 80.46 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	•
104.61	1	59.53	44.7	14.7		210	·

Sampling hualysis Project #19531

0 - 3" Front and Back

[··· · · · · · · · · · · · · · · · · ·		FIUIL AI	IU Back
	A	<u>A</u> .	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6"	Front ar	nd Back
В	В	В
PPM	PPM	PPM
No	No	No


186


6 - 12" Front and Back			
C	С	C	
PPM	PPM	PPM	
No.	No.	No.	

986 423 440 260

271 **504** 439 400

95 213





Restoration Begins: 8/29/97 Restoration Completed: 9/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 47.39 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
61.61	2	15.62	43.55			240	

Sampling Analysis
Project #19531

0 - 3" Front and Back

			IG DOOK
,	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

	В	В	В
P	PM	PPM	PPM
	٧o.	No.	No.

6 - 12" Front and Back


С	C	С
PPM	PPM	PPM
No.	No.	No.

707 416


752 479

474

383



13-8/ sorth of horse is 6/ east of fence.



Restoration Begins: 10/2/97 Restoration Completed: 10/16/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 117.20 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
_(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
152.36	8	52.21	29.7	13.6		360	٠

Sampling Analysis Project #19531

0 - 3" Front and Back

<u> </u>	0 - 0	i ioni ai	ig Dack
	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

431 690

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

282	555
174	160
352	586

6 - 12" Front and Back

C	С	C
PPM	PPM	PPM
No.	No.	No.

690	254
63	57
418	410



10' south of sidemik & 41

\$2- 4' east of sidewilk is all north

Action Date: 4/14/97

Loadout: 4/15/97

Restoration Begins: 4/15/97 Restoration Completed: 5/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 118.30 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TÖPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>
153.8	8	74.37				420	

Sampling Analysis
Project #19531

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

472 **1380**

3 - 6" Front and Back


	I TOTIL CIT	IG DUDIN
В	В	В
PPM	PPM	PPM
No.	No.	No.

427 3100

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

291 **546** 170 **842**



B! - 6'south of Boute ! 4' east 70 power \$596 of 5 den-1K.

B2- 14' west of fence 2' 22' north of hise.

Action Date: 5/27/97 Loadout: 5/28/97

Restoration Begins: 5/28/97 Restoration Completed: 6/13/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 30.5 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Schneider-turf farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR


SPECIAL WASTE

(TONS)

39.65

BACKFILL

(LOADS)



14.1

120

13.45

14.02

Sampling hallysis
Project #19531

0 - 3" Front and Back

	Α	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

237634212438

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

270 **571** 219 **971**

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

57 191



Action Date: 10/4/97

Loadout: 10/8/97

Restoration Begins: 10/8/97

Restoration Completed: 10/16/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 94.02 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill-
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOĪL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>
122.23	1 ,	15.51				240	• ,

Sampling malysis Project #19531

0 - 3" Front and Back

303

188

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

323

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

316 218 **542** 230 **592**

6 - 12" Front and Back

C	С	С
PPM	PPM	PPM
No.	No.	No.

116 32 **621** 137 **620**



BI 7' Sof fonce 8' Wof Lonce Bi 4' Not Long

50% Pared

Action Date: 7/10/97 Loadout: 7/11/97

Restoration Begins: 7/12/97 Restoration Completed: 7/23/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 72.66 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
94.46	4	74.34				420	

Sampling Analysis
Project #19531

0 - 3" Front and Back

		I TOTAL CAL	IG DOOK
1	A	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back


1	В	В	В
ĺ	PPM	PPM	PPM
ĺ	No.	No.	No.

6 - 12" Front and Back
C C C
PPM PPM PPM
No. No. No.


489 **583**

337 **604** 272 **4643**

190 58



X = SAMPLE POINT



Action Date: 10/4/97 - Loadout: 10/9/97

Restoration Begins: 10/9/97

Restoration Completed: 10/21/97

*Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.

*An excavation depth of 3 inches was established by USACE prior to work commencing.

*The excavation of special waste yielded a total of 47.75 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6 CA-7	SAND SOD	CONC
(TONS)	(LOADS) (TONS)	(TONS) (TONS)	(TONS) CU.YDS	· ·
62.08	16		180	

Sampling Analysis Project #19531

0 - 3" Front and Back

		I TOTAL CAL	d Duon
	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back


12	I I OIII C	ailu Duoi
C	С	С
PPM	PPM	PPM
No.	No.	No.

338 **745 699 774**

415 455

148 325





Restoration Begins: 12/16/97 Restoration Completed: 12/18/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 29.89 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

TCM

*17-KW


*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

QUANTITY SUMMARY FOR

SPECIAL WASTE

(TONS) 38.86



180

15.3

Sampling Analysis
Project #19531

0 - 3" Front and Back

	<u> </u>	I I OI IL CII	I'd Daoix
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


C	С	С
PPM	PPM	PPM
No.	No.	No.

345 **541**

510 464

109

360



pet "

Restoration Begins: 5/17/97 Restoration Completed: 6/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 123.86 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SOD	CONCI
:	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS.	
-	161.02	6	68.34	76.59		660	

Sampling Analysis Project #19531

0 - 3" Front and Back

	0 - 0	I TOLIL GI	IG DOON
	Α	· A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

0 12	1 10111		
C	С	С	
PPM	PPM	PPM	
No.	No.	No.	

399 178 415

383 246 **590** 208 **630** 141 46 377



Action Date: 5/1/97

Loadout: 5/5/97

Restoration Begins: 5/8/97

Restoration Completed: 5/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 32.16 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
41.81				17.55	_	150	


Sampling Analysis Project #19531

Street/Number Address

0 - 3"	Front ar	nd Back
Α	Α	. A
PPM	PPM	PPM
No.	No.	No.
42a	526	

3-6" Front and Back					
В	В				
PPM	PPM	PPM			
No.	No.	No.			
480	472				

6-12"	Front and
С	C
PPM	PPM I
No.	No.
312	159



Action Date: 5/1/97

Loadout: 5/5/97

Restoration Begins: 5/5/97 Restoration Completed: 5/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 39.55 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
51.42		74.45	16.25		150	

Sampling Analysis Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

341 309 **655** 3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

604. 243276 389352 699

6 - 12" Front and Back


[С	С	С
Ī	PPM	PPM	PPM
[No.	No.	No.

347 61



X = SAMPLE POINT

(.



Action Date: 5/1/97 Loadout: 5/6/97

Restoration Begins: 5/6/97

Restoration Completed: 5/20/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 127.22 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCE
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	!
165.39	10	90.21	28.35		•	180	•

Sampling Analysis
Project #19531

0 - 3" Front and Back

	√ A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

326 621 128 330 3 - 6" Front and Back


		id Dagit
В	В	В
PPM	PPM	PPM
No.	No.	No.

319 318


6 - 12" Front and Back

C	С	С
PPM	PPM	PPM
No.	No.	No.

511 207 497 274



X = SAMPLE POINT



Action Date: 5/19/97

Loadout: 5/20/97

Restoration Begins: 5/21/97 Restoration Completed: 6/7/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 126.70 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
164.72	3	151.47	29.3	14.5		444	,

Sampling Analysis Project #19531

0 - 3" Front and Back

	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

570 460

3 -	6"	Front	and	Back
-----	----	--------------	-----	------


		id Daoi
В	В	В
PPM	PPM	PPM
No.	No.	No.

530 260 345 232 696 432


6 - 12" Front and Bad	6 -	12"	Fro	nt a	and	l Ba	ck
-----------------------	-----	-----	-----	------	-----	------	----

C	С	С
PPM	PPM	PPM
No.	No.	No.

110 100



X = SAMPLE POINT



Action Date: 7/7/97

Loadout: 7/8/97

Restoration Begins: 7/9/97 Restoration Completed: 7/18/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 57.17 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	_(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
74.33	2	63.27	14.35	13.95		317	_

Sampling malysis
Project #19531

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

	3-0 HORLAND DACE				
В		В	В		
	PPM	PPM	PPM		
	No.	No.	No.		

618

6 - 12" Front and Back

0 12	1 . 0		
С	С	C	
PPM	PPM	PPM	
No.	No.	No.	


402

523

417

230

157



BI 4' from front walk 2' from walk into house B232' from house 2' from walk

House Epavement = 50%

AA

Action Date: 5/12/97(Loadout: 5/13/97

Restoration Begins: 5/14/97 Restoration Completed: 5/20/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 96.49 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

" I CM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
_	125.44	6	31.88		13.5		378	··

Sampling Analysis Project #19531

	0 -	3"	Front	and	Back
--	-----	----	-------	-----	------


	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6	" Front	t and	Back
-------	---------	-------	------

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 -	12"	Front	and	Rack

С	С	С	
PPM	PPM	PPM	
No.	No.	No.	





Restoration Begins: 5/29/97 Restoration Completed: 6/5/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 64.65 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

'TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking


*Schneider Turf Farm


EASEMENT INFORMATION


This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)_:	CU.YDS.	
84.05	3	74.87	14.8			444.5	

Street/Number Address







Restoration Begins: 6/2/97 Restoration Completed: 6/3/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 42.24 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfili
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	_(TONS)_	CU.YDS.	· · · · · · · · · · · · · · · · · · ·
54.92		30.36				190.5	P

0 - 3" Front and Back

<i></i>	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


		500.
C	C	C
PPM	PPM	PPM
No.	No.	No.

846


306

44 749

572



X = SAMPLE POINT



Action Date: 9/8/97 Loadout: 9/11/97

> Restoration Begins: 9/11/97 Restoration Completed: 9/29/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 229.47 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Schneider-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
298.32	5	108.05	76.55	25.35		540	

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back
B B B
PPM PPM PPM
No. No. No.


6 - 12" Front and Back
C C C
PPM PPM PPM
No. No. No.

748

198

574 540

226



Action Date: 9/2/97 Loadout: 9/4/97

Restoration Begins: 9/4/97 Restoration Completed: 9/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 82.88 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Sod Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	· · · ·
107.75	6	42	44.4	14.6		240	

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

	_		
В		В	В
PPN	1	PPM	PPM
No.		No.	No.


660

6 - 12" Front and Back

C	С	С
PPM	PPM	PPM
No.	No.	No.

527 533 404

47



Action Date: 9/2/97

Loadout: 9/3/97

Restoration Begins: 9/5/97 Restoration Completed: 9/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 46.76 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:


*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Sod Farm



0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

	0	, . Oi it ai	id Daoi
	В	В	В
:	PPM	PPM	PPM
	No.	No.	No.


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

700 689

226 337

83





Restoration Begins: 5/13/98 Restoration Completed: 5/19/98

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 42.30 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
55	4		30.5	27.1		360	

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

192

X = SAMPLE POINT



Action Date: 5/15/98 Loadout: 5/16/98

Restoration Begins: 5/18/98 Restoration Completed: 5/21/98

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 49.50 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
64.36	5			14.5		300	

0 - 3" Front and Back

	Α	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

555 99375 3081167 408


3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


87 498


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.



X = SAMPLE POINT





Restoration Begins: 8/7/97 Restoration Completed: 8/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 30.78 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*Kubota

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Sod Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCE
(TONS)	(LOADS)	(TONS)	(TONS)	_(TONS)	(TONS)	CU.YDS.	
40.02		17.33		30.4		60	

0 - 3" Front and Back

	0 0	I I OI IL CI	Id Duon
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back				
С	С	С		
PPM	PPM	PPM		
No.	No.	No.		

524 518 262 317 222 254

63 34 107



Action Date: 8/6/97 Loadout: 8/8/97

Restoration Begins: 8/14/97 Restoration Completed: 9/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 33.16 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*KABOTA

*17-KW

"KABI


*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm



SPECIAL WASTE	1 '			CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
43.12		30.75	14.55	14.65		420	<u> </u>

0 - 3" Front and Back


	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6" Front and Back
B B B
PPM PPM PPM
No. No. No.

6 - 12" Front and Back
C C C
PPM PPM PPM
No. No. No.

545484183

282 162





Restoration Begins: 8/13/97 Restoration Completed: 8/27/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 31.80 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM


*17-KW

*Kubota

*X331

*Subcontractors:

- *WMI-landfill
- *B. Garcia-trucking
- *Granthum-trucking
- *Emerald Sod Farm



Sampling hallysis Project #19531

0 - 3" Front and Back


	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6" Front and Back

	В	В	В
F	PM	PPM	PPM
	No.	No.	No.

6 - 12" Front and Back

C	С	C
PPM	PPM	PPM
No.	No.	No.





Restoration Begins: 11/4/97

Restoration Completed: 11/24/97

*Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.

*An excavation depth of 3 inches was established by USACE prior to work commencing.

*The excavation of special waste yielded a total of 68.25 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
88.73	3.5		16.15	12.85		180	

Sampling Analysis Project #19531

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

319	331		
857	412		

3 - 6" Front and Back


	I TOTAL CAL	IG Daon
В	В	В
PPM	PPM	PPM
No.	No.	No.


188	199
770	397
162	314

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

43	303
176	410





Restoration Begins: 10/31/97 Restoration Completed: 11/24/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 46.70 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
60.72	2	31.24	14.77	13.8		240	

Sampling Analysis Project #19531

0 - 3" Front and Back


	· A	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


379 339 398 **645** 409 3 - 6" Front and Back
B B B
PPM PPM PPM
No. No. No.

218 269 340 463 200 6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

164 152 153 210 193





Restoration Begins: 4/3/97

Restoration Completed: 4/24/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 94.72 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
123.14	3	62	14.65	44.5		180	

Sampling Analysis Project #19531

0 - 3" Front and Back

	Α.	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


C	С	С
PPM	PPM	PPM
No.	No.	No.


707 1481

454 873

299 **1660 637** 144

E





Restoration Begins: 4/30/97 Restoration Completed: 5/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 107.85 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
140.23	5	27.41	90.05	27.46		189	

Sampling hallysis Project #19531

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

600 1270

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

452 673

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

135 **556** 355 **842**



Action Date: 3/26/97 Loadout: 3/28/97

Restoration Begins: 3/29/97 Restoration Completed: 4/24/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 145.11 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.



SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		<u> </u>
188.65	8	163		55.35		300		

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 0	I TOTIL GI	IU Dack
В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back

C	С	С		
PPM	PPM	PPM		
No.	No.	No.		

1330

2700

545



Action Date: 3/26/97

Loadout: 3/28/97

Restoration Begins: 3/29/97 Restoration Completed: 4/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 118.36 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	•
153.89	2	71.09	45.33	25.55		240	

Sampling Analysis Project #19531

0 -	3"	Front	and	Back
-----	----	--------------	-----	------


			5-0.1
	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6" Front and Back

		I JOIN CO	IG DGOIN		
В		В	В		
	PPM	PPM	PPM		
	No.	No.	No.		

6 - 12" Front and Back						
C	С	С				
PPM	PPM	PPM				
No	No	No				

677 270 **625**





Restoration Begins: 6/21/97 Restoration Completed: 7/18/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 138.03 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Schneider-turf farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
179.45	11	107.35	30.55			508	

Sampling nalysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

475

3 - 6" Front and Back

B B B

PPM PPM PPM


No. No. No.

6 - 12" Front and Back					
С	C (C				
PPM	PPM PPM PPM				
No.	No.	No.			

559

564 589

587 318490 825



DRN. BY:

CHKD. BY:

Scale: 1 in = 20ft

Woodward-Clyde Consultants

Engineering & sciences applied to the earth & its environment

Action Date: 11/20/97

Loadout: 11/24/97

Restoration Begins: 11/24/97 Restoration Completed: 12/17/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 159.33 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
207.13	8	32.26	58.9	90.5		420	

Sampling Analysis Project #19531

0 - 3" Front and Back

	A	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6" Front and Back
B B B
PPM PPM PPM
No. No. No.

6 - 12" Front and Back
C C C
PPM PPM PPM
No. No. No.


467 **1574**

175 **875** 339 **1162**

268 331



X = SAMPLE POINT



Action Date: 3/22/97 Loadout: 3/26/97

Restoration Begins: 3/27/97 Restoration Completed: 4/2/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 137.65 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedigo Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	1
178.95	5	47.74	73.09	14.7		283.5	

Sampling malysis Project #19531

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


В	В	В
PPM	PPM	PPM
No.	No.	No.

3 - 6" Front and Back

6 - 12" Front and Back				
C	CC			
PPM	PM PPM PPM			
No.	No.	No.		

598 644 766 721 311 **852 634 612**

234 **2920 1720 1390**



Action Date: 9/9/97

__oadout: 9/11/97

Restoration Begins: 9/12/97

Restoration Completed: 10/21/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 161.02 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
209.33	9	70.63	16.98	34.77		120	

Sampling halysis Project #19531

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


13 16 16 21 435 **943** 3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

13 56 41 21 275 **812** 124 41 6 - 12" Front and Back

. C	С	С
PPM	PPM	PPM
No.	No.	No.

74 80 53 114 304 **546** 105 **623**



Action Date: 10/27/97

Loadout: 10/29/97

Restoration Begins: 10/30/97 Restoration Completed: 11/12/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 218.25 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331 -

*Subcontractors:

*WM1-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	., CA-7	SAND SOD	CONCE
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS.	:
283.73	16	97.44	28.15	14.7	1200	

Sampling Analysis Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1518 311 - 413


3 - 6" Front and Back						
В	В	В				
PPM	PPM	PPM				
No	No	No				

771 542 162 152

6 - 12	" Front a	and Back
С	С	С

С	С	С
PPM	PPM	PPM
No.	No.	No.
NO.	NO.	NO.

250 296 , **256** _



Action Date: 8/26/97 Loadout: 9/3/97

Restoration Begins: 9/3/97 Restoration Completed: 9/17/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 181.56 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*KABOTA

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
236.03	9	47.52	149.3	13.95		477	

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

615 375 479 **515 515**

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

644 318 538580 580

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

898 239 **689 626 626**



Action Date: 4/14/97

Loadout: 4/16/97

Restoration Begins: 4/16/97 Restoration Completed: 5/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 126.25 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM


*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.



Sampling malysis
Project #19531

0 -	3"	Front	t and	Back

	. A	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.


3 - 6" Front and Back


	I TOTIL GI	IG DUOIT
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С		
PPM	PPM	PPM		
No.	No.	No.		

561





1935 Cleveland

Action Date: 7/30/97

Loadout: 8/1/97

Restoration Begins: 8/5/97 Restoration Completed: 8/27/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 75.34 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*Kabota

*X331


- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
97.95	4	53	27.3			240	


Sampling Analysis Project #19531

Street/Number Address

0 - 3"	Front and Back		3-6" Front and Back			6-12" Front and		
A PPM No.	A PPM No.	A PPM No.	B PPM No.	B PPM No.	B PPM No.	C PPM No.	C PPM No.	
348 413	281 109		390 557	360 378		453 144	348 526	



X = SAMPLE POINT



Action Date: 8/1/97 Loadout: 8/6/97

Restoration Begins: 8/6/97 Restoration Completed: 8/27/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 122.98 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*BOMAG

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking


*Grantham-trucking


*Emerald-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>
159.88	6	42.78				510	

Sampling Analysis Project #19531

Street/Number Address





BI - 8' east of sidewalk & 7'

South of sidewalk.

Ba- 121 west of fence 8' north

To paved thouse -

& Appears that front good was tilled.

Action Date: 11/4/97 Loadout: 11/12/97

Restoration Begins: 11/12/97 Restoration Completed: 11/17/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 89.47 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Grantham-trucking
 - *Schneider-turf farm-

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>
116.32	7	47.52		12.85		300	

Sampling Analysis
Project #19531

0 - 3" Front and Back

	A	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back
B B B
PPM PPM PPM

No.

No.

6 - 12" Front and Back							
С	C	C					
PPM	PPM	PPM					
No.	No.	No.					


685 436

326


No.

398

611 816



X = SAMPLE POINT



Action Date: 10/6/97 ✓Loadout: 10/10/97

Restoration Begins: 10/10/97 Restoration Completed: 10/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 75.70 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:


- *WMI-landfill
- *B. Garcia-trucking
- *Granthum-trucking
- *Emerald Turf Farm

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCE
	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	l.
-	98.41	5	44.06		15.05		420	

Sampling Analysis Project #19531

Street/Number Address

0 - 3" Front and Back			3-6" Front and Back			6-12" Front and		
A PPM	A PPM	- -	 B PPM	B PPM	B PPM	C PPM	C PPM	F
No.	No.	No.	No.	No.	No.	No.	No.	
354	1780		536	1610		192	64	



Bi 5'S of front walk 19' W of horse

Or 9'E to garage 15' N to extension of among House & Pavement = 1

Action Date: 10/6/97 Loadout: 10/9/97

Restoration Begins: 10/9/97 Restoration Completed: 10/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 111.71 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
145.31	6	29.99	15.9			420	

Sampling Analysis Project #19531

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

	I I OI IL CII	IG DGOIL
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.


2020 Claudond

662 1780

644 2340

67 **673** 85 **1241**





Restoration Begins: 4/30/97 Restoration Completed: 10/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 74.27 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

- *B. Garcia-trucking
- *Granthum-trucking
- *Schneider Turf Farm

EASEMENT INFORMATION


This easement was completed after the Temporary Restraining Order (TRO) was lifted.

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)_	CU.YDS.	
125.54	2	108.91	14.75			480	

Sampling malysis
Project #19531

0 - 3	3" F	ront	and	Back
-------	------	------	-----	-------------

			بر حص
	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.




6 - 12" Front and Back				
С	С	C		
PPM	PPM	PPM		
No.	No.	No.		


995 194 **686** 485

535 104 447 **519**

155 32



X = SAMPLE POINT



Action Date: 8/18/97 Loadout: 8/20/97

Restoration Begins: 8/22/97 Restoration Completed: 8/28/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 47.63 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*KABOTA

*17-KW

.

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONC
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
61.92		50.79				320	

Sampling Analysis Project #19531

0 -	3"	Fro	ont	and	Bac	k
-----	----	-----	-----	-----	-----	---

		1 10111 41	<u></u> Daoit
	Α	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

340 **715 1671** 212

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

235 411


6 - 12" Front and Back


С	С	C
PPM	PPM	PPM
No.	No.	No.

289 194



X = SAMPLE POINT





Restoration Begins: 8/22/97 Restoration Completed: 9/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 66.81 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCE
(TONS)	(LOADS)	(TONS)	_(TONS)_	(TONS)	(TONS)	CU.YDS.	
86.86		66.95	34.55		*	420	

Sampling malysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back
C C C
PPM PPM PPM

No.


No.

677 552

286 420

100 203

No.



B1 6' to walk into have 12' to front of porch B2 25' N Of Funce

Hoise Eother wrens = 86%

Action Date: 9/30/97

Loadout: 10/1/97

Restoration Begins: 10/2/97

Restoration Completed: 10/21/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 46.36 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	!
60.28	3		12.32	-	180	

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

386 **724** 464 **521**

3 - 6" Front and Back


·B	В	В
PPM.	PPM	PPM
No.	No.	No.


309571174559

6 - 12" Front and Back

		
С	С	C
PPM	PPM	PPM
No.	No.	No.

59 **964** 77 186 106 78





Restoration Begins: 9/19/97

Restoration Completed: 10/13/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 123.04 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCI
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	·
159.96	5	55.38	34.27	19.11	_	180	-

Sampling Analysis Project #19531

0	- 3"	Front	and	Back

	Α	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6"	Front	and	Back
--------	-------	-----	------

В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.


1327

333

610



X = SAMPLE POINT



_\action Date: 4/7/98 Loadout: 4/8/98

Restoration Begins: 4/9/98 Restoration Completed: 4/18/98

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 69.46 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17KW

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

. 9	0.3	11		•			540	
(T(ONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
SPECIA	L WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCF

Sampling analysis Project #19531

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

353 **515** 403 446

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

297 437

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

91 272



B2- 721. IL & harse e' 2' ... L and walk.